



Stream Box S2 Ultra:

New Spotify integration and Spotify Connect with Firmware Update 1.079

The latest Stream Box S2 Ultra Firmware upgrade brings a completely redeveloped Spotify integration along with Spotify Connect!

The update can be installed as per usual within the Stream Box S2 Ultra Web-Interface under System -> System Updates.

Firmware Update 1.079 consists of following changes and improvements:

- Fixed Metadata display for artists and albums
- New Spotify Integration
- Spotify Connect
- Smaller bugfixes and improvements

To use Spotify Connect you don't need to be logged in to Spotify on the Stream Box S2 Ultra. Just do the update, wait until it is installed and the Stream Box has restarted and you'll find it as a Spotify Connect device when clicking the small speaker symbol in the Spotify App.

